

 <p>Not Actual Photo YIC International Co., Limited.</p>	<h2 style="color: #e67e22;">HN27C1024HG-85</h2>
	<p>Manufacturer Part Number: HN27C1024HG-85</p> <p>Manufacturer/Brand: RENESAS</p> <p>Part of Description: RENESAS DIP-40</p> <p>RoHs Status:</p> <p>Stock Condition: New original, 5000 pcs Stock Available.</p> <p>Ship From: Hong Kong</p> <p>Shipment Way: DHL/Fedex/TNT/UPS/EMS</p>
<p>Image may be representation. See specs for product details.</p>	

Specifications

Part Number	HN27C1024HG-85
Manufacturer	RENESAS
Description	RENESAS DIP-40
Category	Integrated Circuits (ICs) > Specialized Hot ICs
Part Status	5000 pcs Stock
Series	-
RoHs Status	Lead free / RoHS Compliant
Condition	New Original Stock
Warranty	100% Perfect Functions
Lead Time	2-3days after payment.
Payment	PayPal / Telegraphic Transfer / Western Union
Shipping by	DHL / Fedex / UPS
Port	HongKong
RFQ Email	Info@Y-IC.com

HN27C1024HG-85 is New Original in Stock, Search HN27C1024HG-85 Datasheets, PDF, Inventory at Y-IC.com Online, Order HN27C1024HG-85 with warrantied and confidence. RFQ HN27C1024HG-85 : Info@Y-IC.com

You May Be Also Be interested

In:

 <p>HN27C1024HGJ-90 HITACHI HITACHI DIP-40PGM</p>	 <p>HN27C256AFP-12T HIT HIT SOP-28</p>	 <p>HN27C256AG-12 HIT HIT DIP-28</p>	 <p>HN27C256G-20 HIT HIT DIP-28</p>
 <p>HN27C1024HCC-85 HI HI PLCC-44P</p>	 <p>HN27C101AG-15 HTI HTI CDIP</p>	 <p>HN27C1024HCP-12 HITACHI HITACHI PLCC</p>	 <p>HN27C1024HCC-10 HIT HIT CPLCC</p>

Hot Parts

[More](#)

- | | | | | |
|--------------------|---------------------|------------------|------------------------|-------------------|
| ⚙️ 2DI75M-050 | ➡️ 2MBI150VG-120-51 | ➡️ 744272221 | D AP3440FNTR-G1 | ➡️ AP6679AGM-HF |
| ⚡ AS6C4016A-45ZIN | ⚙️ AXK7L20227G | D BUK7105-40AIE | ➡️ C1608C0G2A271K080AA | ➡️ CA05P4S14THSG |
| ⚙️ CBL2012T100M | ⚡ DA3X102D0L | ⚙️ DF30DB40 | ➡️ DT95N140F | ➡️ DTD113EKT146 |
| D FDS9953A | ⚙️ HAT2203C-EL-E | ⚡ HCPL-814A | ⚙️ LC4032ZC-75MN56C | ➡️ LD033D104KAB2A |
| ➡️ LL4448-GS08 | ➡️ LM9036QM-5.0 | ⚙️ LX8117-05CDD | ⚡ MAX483CSA+ | ➡️ MAX9790AETJ+T |
| ➡️ MCR01MZSJ330 | ➡️ MDA710-24N1 | D MDC0531ET | ⚙️ MJE15033G | ⚡ MM3Z20-S4032 |
| ⚙️ NJU7250F30-TE1 | D PC817X2NSZ9F | ➡️ PD160FG40 | ➡️ PL3201C-ADV | ➡️ PX3511BDDG-RA |
| ⚡ QS3L384Q | ⚙️ R270SH12 | ➡️ R9G01018XX | ➡️ S9KEAZN8AM | ➡️ SKT351F12DT |
| ⚙️ SN74GTL3004DCKR | ⚡ SP3088EEN | ⚙️ STC12C5202PWM | D STCS05ADR | ➡️ STDP4328-BA |
| ➡️ TC74VHC4053AFT | ⚙️ TDA7850/TDA7560 | ⚡ TDA8566Q | ⚙️ UCC3889DRG4 | ➡️ UWR-12/420-D24 |

Contact us: Info@Y-IC.com

ADD: Unit A5-B5 No.509, 5/F Sing Win Factory Building, 15-17 Shing yip St, Kwun Tong, Kowloon, HongKong.

Copyright © 2019 YIC International Co., Limited